



WORKSHOP REPORT/DIAGNOSIS GUIDE

PT.STAR WAGEN INDONESIA

Date:	7 MARET 2023	Customer Name:	PT. PUTRA PERKASA ABADI	Site:	PT MLP
WIP No:		Reg No :		Reg date:	4-Feb-23
Chassis No:	MFJ400243NJ001235	Type :	2528CX	Mileage / Hours Meter:	4078/323
Engine No:	400953D0128247				
Registration Code:	DA25046				

COMPLAINT ANALYSIS

Customer complaint/Customer information
BRAKE JAMMED/MALFUNTION
Vehicle information
CHAMBER/CYLINDER BRAKE LEAK
System Information
BREAK SYSTEM

TEST LEVEL

Test Level Description	Actual Value	Remark	Attachment Nr
CEK ERROR CODE	OK	OK	
CEK AIR PRESSURE	NOT OK	NOT OK	
CEK KEBOCORAN BREAK SYSTEM	NOT OK	NOT OK	
CEK KEBOCORAN CAMBER BREAK	NOT OK	NOT OK	

CAUSE LEVEL

Cause level/Workshop findings:

	Ada	Tidak ada	Attachment Nr
Photo (# lembar)	√		√
Area kerusakan (gbr EPC)	√		√
Video (nama file)		√	
Old Spare part No.			
Notes:			

LAPORAN DARI OPERATOR UNIT DA25046, BAHWA UNIT MENGALAMI PROBLEM PADA INDIKATOR AIR PRESSURE YANG TIDAK MAU NAIK, SEHINGGA UNIT PADA BREAK SYSTEM TIDAK MAU RELEASE, SETELAH DILAKUKAN PENGECEKAN PADA UNIT, DITEMUKAN ADANYA KEBOCORAN PADA CHAMBER BREAK REAR AXEL 9,10 ACTION YANG DILAKUKAN MENGGANTI CYLINDER/CHAMBER ASSY

RECTIFICATION AND VERIFICATION LEVEL

Rectification:




PART NUMBER	DESCRIPTION	QTY
A4004202224	CAMBER BREAK REAR	1

Verification:

AFINSYAH & ZAENAL Mechanic	 Supervisor/Mgr	Workshop report digunakan untuk mencatat hasil analisa mekanik dengan menyertakan langkah-langkah diagnosis dan temuannya selama diagnosa
-------------------------------	---	---

PICTURE CAUSE AND ACTION			
			
FOTO UNIT	FOTO HM	FOTO KM	FOTO VIN

PICTURE CAUSE AND ACTION			
			
BEFORE PROBLEM	AFTER PROBLEM	PROSES INSTALL	PROSES INSTALL

PICTURE CAUSE AND ACTION			
			
Part Book	picture part no aktual	picture part no part new	PROSES INSTALL