



PUTRA PERKASA ABADI

CLAIM TO:

MERCEDES-BENZ (SWI)

CLAIM NO:

040 / PLT-MIP / CWR / 2023

WARRANTY/POLICY CLAIM FORM

☒ COMPONENT / PART

☐ COMMON (PAP, PPM, VHMS, MAGPLUG, FLUID CONSUMPTION, DLL)

CLAIM DATE : 2023-06-13

COMP. MODEL :

CODE UNIT : DA40041

HM FAILURE : 4105

MODEL UNIT : AROCS 4040K (6X4) A/T

LOCATION UNIT : MIP

SN UNIT : W1T96421620566422

STATUS UNIT : ☒ Operasi
☐ Breakdown

PROBLEM ISSUE

Chasis Crack front RH & LH

SUPPORTING COMMENTS

CLAIM WARRANTY TO MERCEDES-BENZ SWI

FAILED COMPONENT INFORMATION

COMPONENT : CHASSIS

SUB COMPONENT:

PART NUMBER :

QTY : 1

HM/KM FITMENT : 0

HM/KM TROUBLE : 4105

FITMENT DATE : 2022-06-05

TROUBLE DATA : 2023-06-13

LIFETIME : 4105

WARRANTY DECISION

☐ ACCEPT

☐ POLICY/PRORATE

☐ REJECT

SCHEDULE FOLLOW UP

A.S.A.P

APPROVAL

CREATED BY

APPROVED BY

APPROVE BY

FOLLOW UP BY

✓ Approved

✓ Approved

✓ Approved

PUTRA WALUYO FEBRIANTO
PLANT PLANNER

DENNY HADI
PLANT GROUP LEADER/PE

KARDI S. MINGKALA
DEPT/SECTION HEAD PLANT

(.....)
MERCEDES-BENZ (SWI)



PUTRA PERKASA ABADI

CLAIM TO:

MERCEDES-BENZ (SWI)

CLAIM NO:

040 / PLT-MIP / CWR / 2023

FOTO UNIT DEPAN

Tidak ada foto

FOTO UNIT SAMPING

Tidak ada foto

FOTO SN KOMPONEN/UNIT



FOTO HM/KM UNIT




FOTO KOMPONEN YANG RUSAK

