

Selection

Teach-in processes

Release control unit lock.

Transmission variant

Teach in of transmission and clutch

Clutch operating system

Teach-in of clutch

Teach in inclination sensor.

Parameterization

Initial startup

Teach in of transmission and clutch

The following fault has occurred: 11

- An error occurred during teach-in of the clutch.

Possible cause and remedy:

- Check fault memory for current fault codes.
- The supply pressure at component 'Y900 (Transmission positioner)' is too low.
- B503 (Clutch travel sensor)
- The clutch operating system has a mechanical fault.
- The clutch solenoid valves installed in the transmission positioner have a mechanical fault.

Continue

MB_LKW/Steuergeraete/Antrieb/TCM/TCM01T/SFTP/TCM01T_SFTP.gmf#Diagnosis/Adaptions/RuntimeMenu

24.01.2025 10:38:3810/2024W1T96441X20670207 (964.416)

Copyright 2025 Daimler Truck AGPage '1' of '1'