

Caution!

A fault has occurred!

Error 25: The clutch has not been taught in.

Possible cause and remedy

- Check fault memory for current fault codes.
- The supply pressure at component 'Y900 (Transmission positioner)' is too low.
- B503 (Clutch travel sensor)
- The clutch operating system has a mechanical fault.
- The clutch solenoid valves installed in the transmission positioner have a mechanical fault.

Development data: Stopped without results

Development data: Clutch not learned

Development data: Conditions not correct

Development data: learned