



PUTRA PERKASA ABADI

CLAIM TO:**MERCEDES-BENZ (SWI)****CLAIM NO:****047 / PLT-MIP / CWR / 2023**

WARRANTY/POLICY CLAIM FORM

☒ **COMPONENT / PART**☐ **COMMON (PAP, PPM, VHMS, MAGPLUG, FLUID CONSUMPTION, DLL)****CLAIM DATE : 2023-06-14****COMP. MODEL :****CODE UNIT : DA40059****HM FAILURE : 3650****MODEL UNIT : AROCS 4040K (6X4) A/T****LOCATION UNIT : MIP****SN UNIT : W1T96421620566729****STATUS UNIT :**
☒ **Operasi**
☐ **Breakdown**

PROBLEM ISSUE

CHASSIS LH CRACK

SUPPORTING COMMENTS

ACTION SEMENTARA REPAIR BY CUSTOMER

FAILED COMPONENT INFORMATION

COMPONENT : CHASSIS**SUB COMPONENT:****PART NUMBER :****QTY : 1****HM/KM FITMENT : 0****HM/KM TROUBLE : 3650****FITMENT DATE : 2022-07-08****TROUBLE DATA : 2023-06-14****LIFETIME : 3650**

WARRANTY DECISION

☐ **ACCEPT**☐ **POLICY/PRORATE**☐ **REJECT**

SCHEDULE FOLLOW UP

A.S.A.P

APPROVAL

CREATED BY**APPROVED BY****APPROVE BY****FOLLOW UP BY****PUTRA WALUYO FEBRIANTO**
PLANT PLANNER**DENNY HADI**
PLANT GROUP LEADER/PE**KARDI S. MINGKALA**
DEPT/SECTION HEAD PLANT**(.....)**
MERCEDES-BENZ (SWI)



PUTRA PERKASA ABADI

CLAIM TO:

MERCEDES-BENZ (SWI)

CLAIM NO:

047 / PLT-MIP / CWR / 2023

FOTO UNIT DEPAN



FOTO UNIT SAMPING

Tidak ada foto

FOTO SN KOMPONEN/UNIT



FOTO HM/KM UNIT




FOTO KOMPONEN YANG RUSAK

