



PUTRA PERKASA ABADI

CLAIM TO:

MERCEDES-BENZ (SWI)

CLAIM NO:

087 / PLT-MIP / CWR / 2023

WARRANTY/POLICY CLAIM FORM

☒ COMPONENT / PART

☐ COMMON (PAP, PPM, VHMS, MAGPLUG, FLUID CONSUMPTION, DLL)

CLAIM DATE : 2023-09-08

COMP. MODEL :

CODE UNIT : DA40062

HM FAILURE : 4994

MODEL UNIT : AROCS 4040K (6X4) A/T

LOCATION UNIT : MIP

SN UNIT : W1T96421620567811

STATUS UNIT : ☒ Operasi
☐ Breakdown

PROBLEM ISSUE

TGL 4 SEPT 2023 TERDAPAT TEMUAN INSPEKSI, YAITU KETIKA AKAN DOUBLING PLATE CHASSIS DITEMUKAN MINOR CRACK CHASSIS KANAN BAWAH

SUPPORTING COMMENTS

LANGSUNG DILAKUKAN DOUBLING PLATE CHASSIS PADA HARI ITU

FAILED COMPONENT INFORMATION

COMPONENT : CHASSIS

SUB COMPONENT:

PART NUMBER :

QTY : 1

HM/KM FITMENT : 0

HM/KM TROUBLE : 4994

FITMENT DATE : 2022-07-08

TROUBLE DATA : 2023-09-04

LIFETIME : 4994

WARRANTY DECISION

☐ ACCEPT

☐ POLICY/PRORATE

☐ REJECT

SCHEDULE FOLLOW UP

4 SEPT 2023

APPROVAL

CREATED BY

APPROVED BY

APPROVE BY

FOLLOW UP BY

✓ Approved

✓ Approved

✓ Approved

PUTRA WALUYO FEBRIANTO
PLANT PLANNER

DENNY HADI
PLANT GROUP LEADER/PE

KARDI S. MINGKALA
DEPT/SECTION HEAD PLANT

(.....)
MERCEDES-BENZ (SWI)



PUTRA PERKASA ABADI

CLAIM TO:

MERCEDES-BENZ (SWI)

CLAIM NO:

087 / PLT-MIP / CWR / 2023

FOTO UNIT DEPAN



FOTO UNIT SAMPING



FOTO SN KOMPONEN/UNIT



FOTO HM/KM UNIT



FOTO KOMPONEN YANG RUSAK



**CRACK MINOR PADA
CHASSIS SISI KANAN
BAWAH**