



PT. ANTAREJA MAHADA MAKMUR

CLAIM TO: SWI

CLAIM NO: 9 / PLT-SUP-AMM-MHU / CWR / 2024

WARRANTY/POLICY CLAIM FORM

☒ COMPONENT / PART☐ COMMON (PAP, PPM, VHMS, MAGPLUG, FLUID CONSUMPTION, DLL)

CLAIM DATE : 12 April 2024

ENGINE MODEL : AXOR 2528 C

CODE UNIT : FT52507

HM FAILURE : 3737

MODEL UNIT : MERCEDES BENZ

LOCATION UNIT : WORKSHOP BERUAQ

SN UNIT : MFJ400243LJ000113

STATUS UNIT : ☐ OPERASI

REFF. PO : 0

☒ BREAKDOWN

PROBLEM ISSUE

Axle Housing Crack

CHRONOLOGY:

Pada tanggal 12 April 2024 saat unit sedang service dan dilakukan inspeksi, didapatkan temuan berupa adanya kebocoran oli pada Driven Rear Axle. Setelah diamati lebih lanjut, terdapat temuan berupa adanya crack pada welded joint bagian atas axle housing.

FAILED COMPONENT INFORMATION

COMPONENT : DRIVEN REAR AXLE PART NUMBER : A4003504130

SUB COMPONENT : AXLE HOUSING LAST REMOVE (DATE_HM) : 3737

LIFETIME COMP : 3737 JAM LAST INSTALL (DATE_HM) : 0

WARRANTY DECISION

☐ ACCEPT☐ POLICY/PRORATE☐ REJECT

SCHEDULE FOLLOW UP :

APPROVAL

CREATED BY,

YOSUA PW
PLANT ENGINEER

APPROVED BY,

FALANAS FARHAN
PLANNER

APPROVED BY,

ZAINAL ABIDIN
SECTION HEAD PLANT

FOLLOW UP BY,

.....



PT. ANTAREJA MAHADA MAKMUR

CLAIM TO:

SWI

CLAIM NO:

9 / PLT-SUP-AMM-MHU / CWR / 2024

FRONT VIEW




REAR VIEW



SIDE VIEW



VIN




HOUR METER



ODOMETER



REAR AXLE SERIAL NUMBER



REAR DRIVEN AXLE HOUSING



DRIVEN REAR AXLE HOUSING CRACK AT WELDED JOINT



DRIVEN REAR AXLE HOUSING CRACK AT WELDED JOINT

