

**ANTAREJA MAHADA MAKMUR****CLAIM TO:****PT STAR WAGEN INDONESIA****CLAIM NO:****PLT-SITE / CWR / 74 / 1 / 2024 / CWR****WARRANTY/POLICY CLAIM FORM**☒ **COMPONENT / PART**☐ **COMMON (PAP, PPM, VHMS, MAGPLUG, FLUID CONSUMPTION, DLL)**

CLAIM DATE : 28 JANUARY 2024

ENGINE MODEL : ISUZU BB-6BG1 TRJ

CODE UNIT : SV515

HM FAILURE : 430.6

MODEL UNIT : SV700TF

LOCATION UNIT : PITSTOP

SN UNIT : VSV19T-10216

LAST ORDER / PO : 0

STATUS UNIT : ☒ **BREAKDOWN** ☐ **OPERASI****PROBLEM ISSUE**

OPERATOR MENGELUHKAN AC UNIT PANAS KEMUDIAN DI OBSERVASI TERNYATA TERJADI LEAK PADA CONDENSOR AC

SUPPORTING COMMENTS:**AC SYSTEM****FAILED COMPONENT INFORMATION**

COMPONENT : AC SYSTEM

PART NUMBER : 337-9078 (SWITCH GP MAGNETIC) 1PCS

SUB COMPONENT : CONDENSOR AC

LAST REMOVE (HM) : 430.6

LIFETIME COMP : 431 JAM

LAST INSTALL (HM) : 0

WARRANTY DECISION☐ **ACCEPT**☐ **POLICY/PRORATE**☐ **REJECT****SCHEDULE FOLLOW UP :****APPROVAL**

CREATED BY,

M GUNTUR R K
PLANT GROUP LEADER

APPROVED BY,

M GUNTUR R K
PLANT GROUP LEADER

APPROVED BY,

YATO
DEPT/SECTION HEAD PLANT

FOLLOW UP BY,

(.....)
PT STAR WAGEN INDONESIA