

**WORKSHOP REPORT/DIAGNOSIS GUIDE**

PT. STAR WAGEN INDONESIA

Date:	16-Jun-24	Customer Name:	PT. PUTRA PERKASA ABADI	Site	
WIP No:		Reg No :		RTB	
Chassis No:	V170645231208692366	Reg date			16-Jun-24
Engine No:	471922C0802053	Type :	AROCS 4845X E5	Mileage / Hours Meter	5161/519
Registration Code	ANM 9521				

COMPLAINT ANALYSIS

Customer complaint/Customer information

CYLINDER DUMP LEAK

Vehicle information

CYLINDER DUMP
System Information
HYDRAULIC CYLINDER DUMP

TEST LEVEL	TEST TYPE	TEST DATE	TEST RESULT
1	1	1	1
2	2	2	2
3	3	3	3
4	4	4	4
5	5	5	5
6	6	6	6
7	7	7	7
8	8	8	8
9	9	9	9
10	10	10	10
11	11	11	11
12	12	12	12
13	13	13	13
14	14	14	14
15	15	15	15
16	16	16	16
17	17	17	17
18	18	18	18
19	19	19	19
20	20	20	20
21	21	21	21
22	22	22	22
23	23	23	23
24	24	24	24
25	25	25	25
26	26	26	26
27	27	27	27
28	28	28	28
29	29	29	29
30	30	30	30
31	31	31	31
32	32	32	32
33	33	33	33
34	34	34	34
35	35	35	35
36	36	36	36
37	37	37	37
38	38	38	38
39	39	39	39
40	40	40	40
41	41	41	41
42	42	42	42
43	43	43	43
44	44	44	44
45	45	45	45
46	46	46	46
47	47	47	47
48	48	48	48
49	49	49	49
50	50	50	50
51	51	51	51
52	52	52	52
53	53	53	53
54	54	54	54
55	55	55	55
56	56	56	56
57	57	57	57
58	58	58	58
59	59	59	59
60	60	60	60
61	61	61	61
62	62	62	62
63	63	63	63
64	64	64	64
65	65	65	65
66	66	66	66
67	67	67	67
68	68	68	68
69	69	69	69
70	70	70	70
71	71	71	71
72	72	72	72
73	73	73	73
74	74	74	

[illegible]

CAUSE LEVEL

Cause level/Workshop findings:

	Ada	Tidak ada	Attachment No
Photo (# lembar)	✓		✓
Area kerusakan (gbr EPD)	✓		✓
Video (nama file)		✓	

Old Spare part No.
Notes:

PADA TANGGAL 16 JUNI 2021 , UNIT SERVICE 1000HM, DILAKUKAN PRE INSPEKSI DAN DI TEMUKAN KECOBORAN PADA CYL DUMP STEP 1, KEMUDIAN MEKANIK MELAKUKAN PENGCEKKAN DAN COLLECT DATA GUNA WARRANTY .
MOHON SRGBRA DIKIRIM CYLINDER DUMP PENGANTI GUNA MENCBAH UNIT BREAKDOWN UNSCHEDULE

RECTIFICATION AND VERIFICATION LEVEL

Rectification:

PART NUMBER	DESCRIPTION	QTY
	Dump Cyl	1

Verification:

IQBAL

Mechanic

Supervisor/Mgr

Workshop report digunakan untuk mencatat hasil analisa mekanik dengan menyertakan langkah-langkah diagnosis dan temuannya selama diagnosa

PICTURE CAUSE AND ACTION



FOTO UNIT



FOTO HM



FOTO E




FOTO VIN

PICTURE CAUSE AND ACTION



Problem



Problem

Hoist Cylinder Leak



SN CYLINDER