

Alternator failure – regulator functional checking



Vehicle Model	: AXOR 2528 CH
VIN	: MEC2437BAPP132338
TIPS Case date	:
Failure mileage & hourmeter	: 27407KM / 2820H
Alternator batch code	: BATCH KODE HILANG VIDEO TERLAMPIR

- a. Keep the Multimeter **Black probe** at Regulator **Terminal-1** & **Red probe** at Alternator body: 0.4V to 0.6V – **Found OK**, Else **Not OK**



Result:

0,4 V

- b. Keep the Multimeter **Black probe** at Regulator **Terminal-2** & **Red probe** at Alternator body: 0.4V to 0.6V – **Found OK**, Open load (OL) – **Resistor lead cut**



Result:

OL V