


Possible causes of fault

- The fan has a malfunction or is mechanically blocked.
- The parameterization of the fan in control unit 'A4 (Engine management (MCM) control unit)' is invalid.
- Component 'Y616 (Fan clutch solenoid valve)' is defective.



Change view.

Continue

MB_LKW/Steuergeraete/Antrieb/MCM/MCM21T/SFTP/MCM21T_SFTP.gmf#Basisdiagnose/Fehlercodes/Bedatung/670602/Laufzeit