


Possible causes of fault

- The electrical connectors on the affected components are damaged, moist, corroded or loose.
- Component 'Y613 (Cylinder 6 fuel injector)' or its electrical line is defective.

Further notes / Instructions

- The test is started with the 'Continue' button.



Change view.

Continue