

+	Test ID	Test Description	Test Status	Test Category	Test Type	Test Result	Test Action	Test Details
+	5E0002	The fuel pressure in the low-pressure fuel circuit is implausible.	STORED	f				
+	2A1504	Component 'Y642 (Quantity control valve)' or its electrical line has a short circuit to ground.	STORED	f				
+	AE0003	The signal voltage of component 'B602 (Fuel temperature sensor)' is too high.	STORED	f				
+	610003	The signal voltage of component 'B623 (Water separator fill level sensor)' is too high.	STORED	f				
+	5E0004	The signal voltage of component 'B638 (Fuel filter module pressure sensor)' is too low.	STORED	f				
+	76020A	The power supply of the control unit 'A4 (Engine management (MCM) control unit)' was interrupted during operation.	STORED	f				

MB_LKW/Steuergeraete/Antrieb/MCM/MCM21T/SFTP/MCM21T_SFTP.gmf#Diagnosis/FaultCodes/FC