

Possible causes of fault

- Component 'B638 (Fuel filter module pressure sensor)' is defective.

Instruction

- Check component 'B638 (Fuel filter module pressure sensor)' and replace if necessary.

