

DA48104-SEAL HIGH PRESSURE LINE LEAK-FAJAR-Share

Unit : DA48104

Model : AROCS 4845 K


VIN : W1T96423820648680

PROBLEM : SEAL HIGH PRESURE LINE LEAK

P/N : A 472 078 01 80 SEAL High-pressure line to camshaft. Qty 6pcs

A 470 078 08 10 HIGH-PRESSURE LINE 1, 2, & 3. Qty 3pcs

A 470 078 09 10 HIGH-PRESSURE LINE 4, 5, & 6. Qty 3pcs



UNIT & VIN



HM



KM



Issue : Found leakage from Pressure line no.1,2,3,4,5,6.
Corrective : Need Replacement Part