

<

>

↓

↑

Continue

Possible causes of fault

- The power supply for component 'A9 (Truck Control Center (TCC))' is not OK.
- CAN communication between components 'A2 (Central gateway (CGW) control unit)' and 'A9 (Truck Control Center (TCC))' is faulty.
- The coding for component 'A9 (Truck Control Center (TCC))' in control unit 'A2 (Central gateway (CGW) control unit)' is faulty.
- Component 'A9 (Truck Control Center (TCC))' has a malfunction.

MB_LKW/Steuergeraete/Gateway/CGW/CGW04T/SFTP/CGW04T_SFT
P.gmf#Basisdiagnose/Fehlercodes/Bedatung/ALLE_BR/77FFFF/Laufzeit