

WORKSHOP REPORT/DIAGNOSIS GUIDE

PT.STAR WAGEN INDONESIA

Date:	6-Apr-23	Customer Name:	PT. PUTRA PERKASA ABADI	Site	PT MLP
WIP No:		Reg No :		Reg date	11 MARET 2023
Chassis No:	MF 340524 H4A 0001229	Reg No :	252BCX	Mileage / Hours Meter	11513, 67253h
Engine No:	40095205232347				
Registration Code	DA25045				

COMPLAINT ANALYSIS

<u>Customer complaint/Customer information</u>
BRAKE JAMMED/MALFUNCTION
<u>Vehicle information</u>
CHAMBER/LU BRAKE CYLINDER LEAK RR
<u>System Information</u>
BRAKE SYSTEM

TEST LEVEL

[illegible]

CAUSE LEVEL

Cause level/Workshop findings:

	Ada	Tidak ada	Attachment Nr
Photo (# lembar)	√		√
Area kerusakan (gbr EPC)	√		√
Video (nama file)		√	

Notes:

LAPORAN DARI OPERATOR UNIT DA25045, BAHWA UNIT MENGALAMI PROBLEM PADA INDIKATOR AIR PRESSURE YANG TIDAK MAU NAIK, SEHINGGA UNIT PADA BRAKE SYSTEM TIDAK MAU RELEASE, SETELAH DILAKUKAN PENGECEKAN PADA UNIT, DITEMUKAN ADANYA KEBOCORAN PADA CHAMBER BRAKE MIDDLE LEFT AXEL 7&8 ACTION YANG DILAKUKAN MENGGANTI CYLINDER/CHAMBER ASSY 1 PCS

RECTIFICATION AND VERIFICATION LEVEL

Rectification:

PART NUMBER	DESCRIPTION	QTY
A4004202224	CAMBER BREAK REAR	1

Verification:

AFINSYAH & ZAENAL
Mechanic


Supervisor/Mgr

Workshop report digunakan untuk mencatat hasil analisa mekanik dengan menyertakan langkah-langkah diagnosis dan temuannya selama diagnosa

