

## WORKSHOP REPORT/DIAGNOSIS GUIDE

PT.STAR WAGEN INDONESIA

|                   |                    |  |
|-------------------|--------------------|--|
| Date:             | 12 MEI 2023        |  |
| WIP No:           |                    |  |
| Chasis No:        | MFJ400243N.J001218 |  |
| Engine No:        | 400953D0127703     |  |
| Registration Code | DA52521            |  |

|                                        |                       |               |
|----------------------------------------|-----------------------|---------------|
| Customer Name: PT. PUTRA PERKASA ABADI |                       | Site          |
| Reg No :                               |                       | MLP           |
| Reg date                               | 11 DESEMBER 2022      |               |
| Type : 2528CX                          | Mileage / Hours Meter | 14565,3/1677H |

## COMPLAINT ANALYSIS

Customer complaint/Customer information

VOLTAGE BATRAI LOW

### Vehicle information

**ALTERNATOR NOT CHARGING**

## System Information

## ENGINE ELECTRICAL

TEST LEVEL

[illegible]

CAUSE LEVEL

**Cause level/Workshop findings:**

|                          | Ada | Tidak ada | Attachment Nr |
|--------------------------|-----|-----------|---------------|
| Photo (# lembar)         | √   |           | √             |
| Area kerusakan (gbr EPC) | √   |           | √             |
| Video (nama file)        |     | √         |               |
| Old Spare part No.       |     |           |               |

Notes:

Notes:

Pada tanggal 8/05/2023 operator unit DA52521., BAHWA PANEL BATRAY NYALA, DAN LAMPU INSTRUMEN TDK BERFUNGSI SEMUA, SETELAH DI LAKUKAN PENGECEKAN DI TEMUKAN BAHWA ALTERNATOR NOT CHARGING, PENGGANTIAN ALTERNATOR ASSY MENGGUNAKAN STOK LOGISTIC

## RECTIFICATION AND VERIFICATION LEVEL

**Rectification:**

| PART NUMBER        | DESCRIPTION       | QTY      |
|--------------------|-------------------|----------|
| <b>A4001500250</b> | <b>ALTERNATOR</b> | <b>1</b> |

**Verification:**

  
**AFINSYAH & ZAENAL**  
Mechanic

Supervisor/Mgr

Workshop report digunakan untuk mencatat hasil analisa mekanik dengan menyertakan langkah-langkah diagnosis dan temuannya selama diagnosa

