

WORKSHOP REPORT/DIAGNOSIS GUIDE

PT.STAR WAGEN INDONESIA

Date:	3 MARET 2023	Customer Name:	PT. PUTRA PERKASA ABADI	Site	PT MLP
WIP No:		Reg No :		Reg date	4-Feb-23
Chasis No:	MFJ400243NJ001235	Type :	2528CX	Mileage / Hours Meter	3663/277
Engine No:	400953D0128247				
Registration Code	DA25046				

COMPLAINT ANALYSIS

Customer complaint/Customer information

LEAKING FIUL ENGIN

Vehicle information

Vehicle information

LU PRESURE LINE CRACK

System Information

FIUL SISTEM

TEST LEVEL

[illegible]

CAUSE LEVEL

Cause level/Workshop findings:

	Ada	Tidak ada	Attachment Nr
Photo (# lembar)	√		√
Area kerusakan (gbr EPC)	√		√
Video (nama file)		√	

LAPORAN DARI OPERATOR UNIT DA25046 TERJADI KEBOCORAN FEUL PADA ENGIN, SETELAH DILAKUKAN PENGECEKAN DITEMUKAN ADANYA KEBOCORAN PADA LU PRESURE LINE NOZZEL NO5

RECTIFICATION AND VERIFICATION LEVEL

Rectification:

PART NUMBER	DESCRIPTION	QTY
A9060702433	LU PRESSURE LINE	1

Verification:

AFINSYAH & ZAENAL
Mechanic

Supervisor/Mgr

Workshop report digunakan untuk mencatat hasil analisa mekanik dengan menyertakan langkah-langkah diagnosis dan temuannya selama diagnosa

