



Truck & Bus
in Indonesia

PT Star Wagen Indonesia

Authorized Dealer of Mercedes-Benz Truck & Bus in Indonesia

Final Control Report

Customer Name : PT. PUTRA PERKASA ABADI
Wo no/ WIP NO : 3.1E+11

Millage In : 1668.9
Millage Out : 1668.9

Check And Tested By
Name : CANDRA / DANI
Date : 26 MEI 2023

Function Checks	
<input checked="" type="checkbox"/>	All warning indicators
<input checked="" type="checkbox"/>	Steering system
<input checked="" type="checkbox"/>	Horn
<input checked="" type="checkbox"/>	Lights interior / exterior
<input checked="" type="checkbox"/>	Other electrical equipment
<input checked="" type="checkbox"/>	Central locking / closing assist system
<input checked="" type="checkbox"/>	Brakes on dynamometer or test drive
<input checked="" type="checkbox"/>	Air conditioner

Fluid Levels	
<input checked="" type="checkbox"/>	Engine
<input checked="" type="checkbox"/>	Transmission
<input checked="" type="checkbox"/>	Radiator / Coolant
<input checked="" type="checkbox"/>	Power steering
<input checked="" type="checkbox"/>	Battery
<input checked="" type="checkbox"/>	Brake system
<input checked="" type="checkbox"/>	Windshield washer

Visual Checks	
<input checked="" type="checkbox"/>	Engine
<input checked="" type="checkbox"/>	Transmission
<input checked="" type="checkbox"/>	Rear axles
<input checked="" type="checkbox"/>	Steering system
<input checked="" type="checkbox"/>	Fuel system
<input checked="" type="checkbox"/>	Cooling system
<input checked="" type="checkbox"/>	Brake hoses / lines / linkage
<input checked="" type="checkbox"/>	Condition of tires/spare tires (if any)
<input checked="" type="checkbox"/>	Cleanliness inside and outside
Final Checks	
<input checked="" type="checkbox"/>	Check work performed
<input checked="" type="checkbox"/>	Test Drive if needed

Other Checks	
<input checked="" type="checkbox"/>	Wiper blades and spraying nozzle
<input checked="" type="checkbox"/>	Vacuum hoses/lines
<input checked="" type="checkbox"/>	Write your own checking list related repair you did
<input checked="" type="checkbox"/>	CHECK KEBOCORAN ANGIN PIPA COMPRESSOR
<input checked="" type="checkbox"/>	CHECK KAPASITAS ANGIN PADA INDIKATOR ANGIN
Document Check	
<input checked="" type="checkbox"/>	Test document / Short test result
<input checked="" type="checkbox"/>	Workshop report (only if required)
<input checked="" type="checkbox"/>	Internal part requisition slip
<input checked="" type="checkbox"/>	Battery test result, only if tested

By you, we performed a final quality check on your vehicle with the following results:

Ok ☐ No ☐

During the repair process, some critical findings have to be followed up:

- 1.
- 2.

Approved on to but not approved for doing an action.

Muhamad Suprayono
(Service Advisor)

(Customer)

Acknowledged by

Foreman or Supervisor