

VIN	MFJ400243NJ001257	Model series/model designation	HDT
Order number		License plate	

02622 : Switch group 2/3 has   +.

Figure legend :

- A3: Control unit CPC Common Powertrain Controller
- S7: Reverse gear switch
- B5: Parking brake switch
- S9: Neutral position switch

Possible causes of fault :

- Output X1 18/12 has   -.
- Output x3 21/5 has   -.
- Output x3 21/9 has   -.
- Output X4 18/12 has   -.

Filename: C:\TesterUpdate\Data\mnt\active\DAS\bin\..\trees\BharatBenz\fr\frhdt1\kil\FRx2622-.s

Cell co-ordinate: 7 , 4