

VIN	MFJ400243NJ001257	Model series/model designation	HDT
Order number		License plate	

01125 : D+ connection X4 18/13 plausibility/ –//– / ┐ ┘ –

Figure legend :

- A3: Control unit CPC Common Powertrain Controller
- G2: Generator
- X4: Connector (18-pin)
- X2.1: Cab connection

Possible causes of fault :

- Cable X4 18/13 - G2/D+ may have –//– or ┐ ┘ –.
- Generator or regulator faulty
- Actual value 27 can be used for troubleshooting.

Filename: C:\TesterUpdate\Data\mnt\active\DAS\bin\..\trees\BharatBenz\fr\frhdt1\ki\EFRX112-5.s

Cell co-ordinate: 7 , 2