



WORKSHOP REPORT/DIAGNOSIS GUIDE

PT.STAR WAGEN INDONESIA

Date:	11 MARET 2023	Customer Name: PT. PUTRA PERKASA ABADI	Site
WIP No:		Reg No :	PT MLP
Chasis No:	MFJ400243NJ001235	Reg date	11 MARET 2023
Engine No:	400953D0128247	Type :	4620/386
Registration Code	DA25046	Mileage / Hours Meter	

COMPLAINT ANALYSIS

Customer complaint/Customer information				
---	--	--	--	--

KEBOCORAN FIUL PADA ENGINE

Vehicle information

LU PRESUR LIM

System Information

TEST LEVEL

[illegible]

CAUSE LEVEL

Cause level/Workshop findings:

	Ada	Tidak ada	Attachment Nr
Photo (# lembar)	√		√
Area kerusakan (gbr EPC)	√		√
Video (nama file)		√	

Old Spare part No.	
--------------------	--

LAPORAN DARI OPERATOR UNIT DA25046 , BAHWA TERJADI KEBOCORAN FUEL PADA AREA ENGINE , YG MENGAKIBATKAN UNIT MENGALAMI LOW POWER , SETELAH DILAKUKAN PEGECEKAN PADA UNIT DITEMUKAN ADANYA KEBOCORAN PADA LU PRESSURE NOZZEL NO. 2 . DAN DILAKUKAN PENGANTIAN PART PADA UNIT SESUAI KERUSAKAN

RECTIFICATION AND VERIFICATION LEVEL

Rectification:

PART NUMBER	DESCRIPTION	QTY
A9060702433	LU PRESSURE LINE	1


Verification:

AFINSYAH & ZAENAL
Mechanic

Supervisor/Mgr

Workshop report digunakan untuk mencatat hasil analisa mekanik dengan menyertakan langkah-langkah diagnosis dan temuannya selama diagnosa

		PICTURE CAUSE AND ACTION	
			
BEFORE PROBLEM	AFTER PROBLEM	PROSES INSTALL	PROSES INSTALL

PICTURE CAUSE AND ACTION																					
 Part Book	 picture part no actual																				
07.001 Unit Pump & Injection Nozzle MODEL NAME : X CXD EURO4 <table border="1"> <thead> <tr> <th>ITEM NO</th> <th>PART NUMBER</th> <th>DESCRIPTION</th> <th>QTY</th> <th>REMARKS</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>A0200749002</td> <td>LU UNIT PUMP, PLD</td> <td>6</td> <td></td> </tr> <tr> <td>2</td> <td>A9069900001</td> <td>B1 HEXAGONAL BOLT</td> <td>12</td> <td></td> </tr> <tr> <td>3</td> <td>A9060702433</td> <td>LU PRESSURE LINE</td> <td>6</td> <td></td> </tr> </tbody> </table> picture part no part new	ITEM NO	PART NUMBER	DESCRIPTION	QTY	REMARKS	1	A0200749002	LU UNIT PUMP, PLD	6		2	A9069900001	B1 HEXAGONAL BOLT	12		3	A9060702433	LU PRESSURE LINE	6		PROSES INSTALL
ITEM NO	PART NUMBER	DESCRIPTION	QTY	REMARKS																	
1	A0200749002	LU UNIT PUMP, PLD	6																		
2	A9069900001	B1 HEXAGONAL BOLT	12																		
3	A9060702433	LU PRESSURE LINE	6																		