



PUTRA PERKASA ABADI

CLAIM TO:

MERCEDES-BENZ (SWI)

CLAIM NO:

066 / PLT-MIP / CWR / 2023

WARRANTY/POLICY CLAIM FORM

☒ COMPONENT / PART

☐ COMMON (PAP, PPM, VHMS, MAGPLUG, FLUID CONSUMPTION, DLL)

CLAIM DATE : 2023-07-02

COMP. MODEL :

CODE UNIT : DA40047

HM FAILURE : 4339

MODEL UNIT : AROCS 4040K (6X4) A/T

LOCATION UNIT : MIP

SN UNIT : W1T96421620570536

STATUS UNIT : ☒ Operasi
☐ Breakdown

PROBLEM ISSUE

CHASSIS CRACK (RH-LH)

SUPPORTING COMMENTS

CLAIM WARRANTY TO SWI

FAILED COMPONENT INFORMATION

COMPONENT : CHASSIS

SUB COMPONENT:

PART NUMBER :

QTY : 1

HM/KM FITMENT : 0

HM/KM TROUBLE : 4339

FITMENT DATE : 2023-06-05

TROUBLE DATA : 2023-07-02

LIFETIME : 4339

WARRANTY DECISION

☐ ACCEPT

☐ POLICY/PRORATE

☐ REJECT

SCHEDULE FOLLOW UP

A.S.A.P

APPROVAL

CREATED BY

APPROVED BY

APPROVE BY

FOLLOW UP BY

✓ Approved

✓ Approved

✓ Approved

PUTRA WALUYO FEBRIANTO
PLANT PLANNER

DENNY HADI
PLANT GROUP LEADER/PE

KARDI S. MINGKALA
DEPT/SECTION HEAD PLANT

(.....)
MERCEDES-BENZ (SWI)



PUTRA PERKASA ABADI

CLAIM TO:

MERCEDES-BENZ (SWI)

CLAIM NO:

066 / PLT-MIP / CWR / 2023

FOTO UNIT DEPAN



FOTO UNIT SAMPING

Tidak ada foto

FOTO SN KOMPONEN/UNIT



FOTO HM/KM UNIT




FOTO KOMPONEN YANG RUSAK

