

VIN	MEC2437BAPP132138	Model series/model designation	HDT
Order number	License plate		

10104 : CAN link to CPC Common Powertrain Controller faulty

Figure legend :

- A6: Control unit MR engine control
- A3: Control unit CPC Common Powertrain Controller
- X1, X2.2, X4: Plug connections

Note :

- It is not possible to process the fault code either as a current or as a stored fault as no communication with control unit MR engine control is possible.

Instruction :

- Check CAN link to control unit CPC Common Powertrain Controller.
- Inspect cables, connectors, plug connections and electrical components for damage, correct connection, loose contact and corrosion, and repair if necessary.
- Process engine CAN bus fault in control unit CPC Common Powertrain Controller.
- Carry out operational check.
- Communication with control unit MR engine control re-established: Check parameterization of control unit MR engine control for single-wire capability.

Filename: C:\TesterUpdate\Data\mnt\active\DAS\bin\..\trees\bharatbenz\mr\mrhdt2\af\fmrx01-04.s

Cell co-ordinate: 5 , 5