

VIN	MEC2437BAPP132138	Model series/model designation	HDT
Order number		License plate	

3002: Control unit CPC Common Powertrain Controller has failed.

Figure legend :

- A3: CPC Common Powertrain Controller
- Z1: Vehicle CAN bus star point

Test of cable and star point :

- Switch off ignition.
- Unplug connector X2 at control unit CPC Common Powertrain Controller.
- X2 18/18  X2 18/16
- Specified value: 54-66 ohms

Question :

- Is the measured value within the specified value range?

Filename: C:\TesterUpdate\Data\mnt\active\DAS\bin\..\trees\BharatBenz\in\inhdt1\af\FINX300-2.s
Cell co-ordinate: 31 , 4