

DA 54829-WORKING CYL LEAK-TUBAGUS

PN : A 000 466 55 92

NAME : WORKING CYLINDER

Unit : DA 54829

VIN : W1T96423120658614

HM : 438 H


Stts : operasi



UNIT





VIN



HM



KM



PARTBOOK

Issue : During the Periodic Inspection we found that steering cylinder was leak at HM 438 hrs.
Corrective : Need replacement cylinder, unit running with note