

PT. STAR WAGEN INDONESIA

Chamber Brake Hit Cross Member

AXOR 2528 CH

FUEL TRUCK

FT52510

PPA-MIP

VIN : MFJ400243PJ002146

HM : 48 Hrs


KAROSERI SIGMA

PT. Star Wagen Indonesia– Authorized Dealer Of
Mercedes Benz Truck In Indonesia

Data Unit – FT52510



Foto Unit



VIN




HM



KM

TEMUAN PROBLEM– FT52510



**2 Chamber Brake Rear mengalami gesekan/
berbenturan dengan cross member**

**Dengan kondisi tersebut akan menimbulkan potensi
merusak chamber brake dan mengakibatkan air
pressure leak.**



**Detail Kontak antara upper chamber brake
dengan bottom cross member**

