

**ANTAREJA MAHADA MAKMUR**

CLAIM TO: PT.STARWAGEN INDONESIA

CLAIM NO: PLT-SITE / CWR / 156 / 7 / 2024 / CWR

WARRANTY/POLICY CLAIM FORM☒ COMPONENT / PART☐ CONMON (PAP, PPM, VHMS, MAGPLUG, FLUID CONSUMPTION, DLL)

CLAIM DATE : 25 JULY 2024

ENGINE MODEL : OM906 EURO IV

CODE UNIT : DA52529

HM FAILURE : 1810

MODEL UNIT : MERCEDES-BENZ

LOCATION UNIT : PIT

SN UNIT : MFJ400243PJ002312

LAST ORDER / PO : 0

STATUS UNIT : ☐ BREAKDOWN ☒ OPERASI**PROBLEM ISSUE**

SUBFRAME CRACK

SUPPORTING COMMENTS:**SUBFRAME****FAILED COMPONENT INFORMATION**

COMPONENT : SUBFRAME

PART NUMBER :

SUB COMPONENT : SUBFRAME

LAST REMOVE (HM) : 1810

LIFETIME COMP : 1810,0 JAM

LAST INSTALL (HM) : 0

WARRANTY DECISION☐ ACCEPT☐ POLICY/PRORATE☐ REJECT

SCHEDULE FOLLOW UP :

APPROVAL

CREATED BY,

APPROVED BY,

APPROVED BY,

FOLLOW UP BY,

HARBI SAHPUTRA
PLANT GROUP LEADERHARBI SAHPUTRA
PLANT GROUP LEADERYATO
DEPT/SECTION HEAD PLANT(.....)
PT.STARWAGEN INDONESIA



ANTAREJA MAHADA MAKMUR

CLAIM TO:

PT.STARWAGEN INDONESIA

CLAIM NO:

PLT-SITE / CWR / 156 / 7 / 2024 / CWR

POSISI CRACK

