

KEPADA (Sold To): **PT. SUKSES MANDIRI BERKAH**

PT Star Wagen Indonesia
Authorized Dealer of Mercedes-Benz Truck in
Indonesia
Authorized Distributorship SAKAI

No WO: **310000010374**

No	Unit model	Serial Number/ VIN Unit	KM/HM	Engine Model	Engine Number	Kode Unit
1	2SV70 - 10917	2SV70 - 10917	1.96A	4B91	148142	SV526D

Unit tersebut telah dilaksanakan perbaikan:

No	Description Job	Hasil (Result)	Keterangan (Remarks)
1	REPLACE SEAL INPUT SHAFT	FINISH	
2	DRIVE PUMP		
3			

Mekanik **PT Star Wagen Indonesia** dan Petugas Lapangan **Customer** telah melaksanakan Test Operasi secara bersama - sama, dengan kesimpulan: Unit/Komponen dalam kondisi BAIK dan SIAP PAKAI.

Dengan ditandatanganinya BAPP ini, maka pekerjaan dan seluruh dokumentasi administrasi sudah siap untuk dilanjutkan ke proses berikutnya. Demikian Berita Acara Penyelesaian Pekerjaan kami buat dengan sesungguhnya dan dapat digunakan sebagaimana mestinya.

PT. SUKSES MANDIRI BERKAH

Sarwo

Nama: **SARWO**
Tanggal: **19/7/24**

PT Star Wagen Indonesia

STAR WAGEN
INDONESIA

Mekanik: **M. RFA - RFAI**
Tanggal: **19 - 07 - 2024**



ACTIVITY REPORT
Catatan Detail Yang Dilakukan Mekanik

Nama Customer	PT. SMBS		
Unit Model	SV 526 D		
Kode Unit	2SV70 - 10917		
Engine Model	4BG1 -		
KM		HM	1964

NO WO	31 00000 10374
Branch/Site	JAKARTA

Date	Time		Description Of Work (Tindakan yang dilakukan)	Total Time
	Start	End		
16-7-24	08:00	20:00	- Travel To Probolinggo	
17-7-24	08:00		- Preparation	
			- R&I Engine Hood	
			- R&I Hyd Pump	
			- R&I Flywheel	
			- R&I Hose Hyd Line	
		17:00	- Final Inspection	
18-7-24	08:00		- Ground Test	
			- Check Pressure Drive Pump	
			- Check Pressure Charge Pump	
			- Check Pressure Amplitud	
		17:00	- Final Test	
19-7-24	08:00	20:00	- Travel to Jakarta	

Mengetahui,		SWI Department Service	
Nama Customer :		Report By : M. IREDA . RIFA	
Jabatan :		NRP : 23001366	
No HP	Sarwo	No HP : 085 878784110	Name : Service Manager/Supervisor