


ANTAREJA MAHADA MAKMUR
CLAIM TO: PT. STAR WAGEN INDONESIA

CLAIM NO:

PLT-SITE / CWR / 197 / 10 / 2025 / CWR

WARRANTY/POLICY CLAIM FORM
☒ COMPONENT / PART

☐ COMMON (PAP, PPM, VHMS, MAGPLUG, FLUID CONSUMPTION, DLL)

CLAIM DATE : 06 OCTOBER 2025

ENGINE MODEL : WP13G530E310

CODE UNIT : HS5002

HM FAILURE : 2736,1

MODEL UNIT : SKT105S

LOCATION UNIT : GTR

SN UNIT : KT105ASE40913

LAST ORDER / PO : 0

 STATUS UNIT : ☒ BREAKDOWN ☐ OPERASI

PROBLEM ISSUE

Alternator jammed & belt broken

SUPPORTING COMMENTS:

Need checking condition of Alternator/generator until belt adjuster, cause indication jammed

FAILED COMPONENT INFORMATION

COMPONENT : ALTERNATOR

PART NUMBER : 160899000348A

SUB COMPONENT : ALTERNATOR

LAST REMOVE (HM) : 2736,1

LIFETIME COMP : 2736,1 JAM

LAST INSTALL (HM) : 0

WARRANTY DECISION
☐ ACCEPT

☐ POLICY/PRORATE

☐ REJECT

SCHEDULE FOLLOW UP :

APPROVAL

CREATED BY,

 ARGA YOGA P
PLANT GROUP LEADER

APPROVED BY,

 BUYUNG CHANDRA
PLANT GROUP LEADER

APPROVED BY,

 SUPRIYANTO
DEPT/SECTION HEAD PLANT

FOLLOW UP BY,

 (.....)
PT. STAR WAGEN INDONESIA





ANTAREJA MAHADA MAKMUR

CLAIM TO:

PT. STAR WAGEN INDONESIA

CLAIM NO:

PLT-SITE / CWR / 197 / 10 / 2025 / CWR



184 Power System

SKT105ARS

180102130004A089 Generator Combination Group					
INDEX	PART NO.	DESCRIPTION	Remark	QTY	SEE PAGE
1	61000719	Nut		1	
2	18089900348A	Generator		1	
3	61000739	Hex Head Bolt		1	