STAR WAGEN INDONESIA member of PPA

Recommended Part List

Doc. Number : SWI-QA-FORM.06-RPL
Issuance Date : 16 Maret 2025
Revision : 00
Responsibility : SERVICE
Page : 1 of 1

WO. NUMBER :	COMPONENT : ENGINE	SITE ORIGIN : AMI
UNIT NO : DA25136	PN COMPONENT :	FAILURE DESC. : CAMSHAFT WORN OUT
MODEL_SN UNIT : MEC2437BAPP131804	HOURS COMPONENT : 8060	WORK DESC. : OVH ENGINE

NO	COMPONENT GROUP	ITEM NO. OF GROUP	PART NUMBER	PART NAME	QTY	REMARK / FAILURE DESCRIPTION
1	CAMSHAFT	2	A9060541401	CAM FOLLOWER / NORMAL	12	BASIC OVH
2	Cylinder Head	39	A9060161420	CYLINDER HEAD GASKET	1	BASIC OVH
3	CAMSHAFT	5	A9060504201	ZB CAMSHAFT COMPL	1	CHAMSHAFT WORN OUT
4	Timing Case	5	A0259975047	SHAFT LIP TYPE SEAL / CRANKSHAFT RR	1	BASIC OVH
5	Unit Pump & Injection Nozzle	1	A0280749002	LU UNIT PUMP, PLD	1	CAMSHAFT BROKEN
6	Unit Pump & Injection Nozzle	6	A4000910280	GASKET (FUEL FEED PUMP)	1	BASIC OVH
7	Exhaust Manifold	4	A4001420480	GASKET	3	BASIC OVH
8	Exhaust Manifold	2	A9049900412	LU COMBI-SCREW WITH BIHEXAGON SOCKET	12	BASIC OVH
			A0289975648	seal PLD	5	BASIC OVH
			A0239976848	seal return PLD	5	BASIC OVH
				TOTAL		

Mechanic Note :

PJO Note :

Prepared by,	Checked by,	Reviewed by,	Approved by,
M Khalim	Didik Indriyanto Utomo	.....	Sigit Purwanto
MECHANIC	LEADER	QUALITY ASSURANCE	PJO / SUPERVISOR SERVICE
Date :			